

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. NAVAL BASE, PEARL HARBOR, LATRINE DRY DOCK
NO. 2 & LATRINE DRY DOCK NO.3
(U.S. Naval Base, Pearl Harbor, Naval Shipyard, Facility Nos. 171 &
208)
Near Avenue G adjacent to Dry Dock No. 2 & Dry Dock No. 3
Pearl Harbor
Honolulu
Hawaii

HABS HI-482

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Franzen, photographer, December 2000 and February 2001

HI-482-1	Facility 208 - Oblique exterior view of east and south sides. View facing northwest
HI-482-2	Facility 208 - Oblique view from north. "Crane Construction Zone". View facing south.
HI-482-3	Facility 208 - View of east side. View facing west-northwest
HI-482-4	Facility 208 - North end view. View facing south-southwest
HI-482-5	Facility 208 - Detail of two entry doors on the west side of the facility. View facing south
HI-482-6	Facility 208 - Men's bathroom overview showing piping for old second-story bathroom. View facing west-southwest
HI-482-7	Facility 208 - Men's bathroom showing cut out walls. View facing west
HI-482-8	Facility 208 - Stairwell with brass rails and treads. Original round corner tile work. View facing southwest
HI-482-9	Facility 171 - Oblique exterior view of west facade and south side
HI-482-10	Facility 171 - Oblique exterior view of east and north sides
HI-482-11	Facility 171 - View of north side

U.S. NAVAL BASE, PEARL HARBOR, LATRINE DRY DOCK

HABS HI-482
INDEX TO PHOTOGRAPHS
Page 2

HI-482-12	Facility 171 - View of west side
HI-482-13	Facility 171 - Interior view of stair. Door to bathroom on left side of photo
HI-482-14	Facility 171 - Interior view of second floor shower room, showing original tile and metal ventilation louvers
HI-482-15	Facility 171 - Interior view of second floor hall showing original tile and windows. View facing north